

v3.2.1.0 Release Notes

v3.2.1.0 is released for ESP32. The changes since the [v3.2.0.0](#) are as follows.

ESP32-AT

Documentation for Release v3.2.1.0 is available at <https://docs.espressif.com/projects/esp-at/en/release-v3.2.0.0/esp32/index.html>. ESP32-AT v3.2.1.0 is a minor update for ESP32-AT [v3.2.0.0](#).

The firmwares:

- [ESP32-WROOM-32-AT-V3.2.1.0.zip](#)
- [ESP32-SOLO-AT-V3.2.1.0.zip](#)
- [ESP32-PICO-D4-AT-V3.2.1.0.zip](#)
- [ESP32-MINI-1-AT-V3.2.1.0.zip](#)

This is the list of changes since release [v3.2.0.0](#):

Optimization

- Optimized the time cost of the [AT+BLEGATTSSRVCRE](#) command by removing some logs